


STAVE N15 report

Electrical/ Functional tests before thermalcycling


1911/2013

IV measurements

IV_3D




IV_planar




Bad pixel per FE

bad_pixel_sum




Overall bad pixel

NumberBadPixelsOnStave



Threshold

Threshold Mean Value



Noise

Sigma Threshold Mean Value

